

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:				
	Steven Fluke Environmental Scientist II			
OGM	Joe Helfrich Environmental Scientist III			
Company	Dan Guy			

Inspection Report

Permit Number:	C0070016		
Inspection Type:	TECHNICAL		
Inspection Date:	Tuesday, July 20, 2004		
Start Date/Time:	7/20/2004 9:30:00 AM		
End Date/Time:	7/20/2004 12:00:00 PM		
Last Inspection:			

Inspector: Steven Fluke, Environmental Scientist II

Weather: Mostly cloudy, calm, ~75 F
InspectionID Report Number: 342

Accepted by: whedberg

8/8/2004



Permitee: MOUNTAIN COAL CO
Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Assesses

Current Acreages		Mineral Ownership	types of Operation		
180.00	Total Permitted	✓ Federal	✓ Underground		
 34.88	Total Disturbed	☐ State	Surface		
	Phase I	\Box County	☐ Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	☐ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Joe Helfrich and I conducted this inspection as the Hydro/Inspector Visit that was to be conducted first quarter 2004. Due to scheduling conflicts, the inspection was postponed until this visit. We met with Dan Guy at 9:30 am and hiked from the sediment pond area to spring site 2-10-W. The purpose of the visit was for me to get more acquainted with the site and see the water monitoring locations.

Inspector's Signature

St 7lh

Date

Wednesday, July 21, 2004

Steven Fluke, Environmental Scientist II

Inspector ID Number: 53

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070016 Inspection Type: TECHNICAL

Inspection Date: Tuesday, July 20, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V		V	
4.d	Hydrologic Balance: Water Monitoring	✓		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches		annersal.		
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.1	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070016 Inspection Type: TECHNICAL

Inspection Date: Tuesday, July 20, 2004

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first sediment pond contained some water and the other two were dry as usual. Dan stated that he could only remember one time when the other ponds held water. There was no water in Jacobs pond which is fed by the spring at 2-10-W. The spring area was wet, but there was no flowing water.

4.c Hydrologic Balance: Other Sediment Control Measures

There is some sediment in the riprap stream channel that joins the main stream from the north just downstream of 2-9-W. The sediment is the result of a logging company's road grading outside of the permit area completed two years ago that caused sediment to wash into the permit area. The road has been repaired and the riprap channel appears stable with no new/additional sediment.

4.d Hydrologic Balance: Water Monitoring

My main goal of the hydro/inspector visit was to see the monitoring locations to get a better understanding of the site when reviewing the water monitoring data. We didn't hike beyond 2-10-W to the edge of the permit boundary, so I haven't seen monitoring station 2-7-W.